Status on ecl trigger

2024/10/02 B2GM Y.Unno

ETM


- Newly send N(TC) for FW, BR, BW separately to GDL
 - Will be utilized at GDL for updated injection veto
- Start sending all TC data to GNN-ETM
 - one transceiver(4lines,GTY) with YungTsung protocol
 - counter+revo + 576 x [hit(1)+timing(7), energy(12)]
- Investigation of instability of TMM-ETM link after firmware reboot is (slowly) in progress…

GNN-ETM

- VU190 installation at ehut done.
 - Cabling (PCle40, FTSW, GDL, ETM, clock) done
- Simple online software w/ ecltrg library prepared
 - Status check(clk,b2tt,b2l), reboot, mcs load
- Receiving all 576 TC data from ETM w/ one transceiver(4lines,GTY)
- 1st version of GNN-ETM with b2link by Marc
- Test of b2link in progress
 - Thanks to Yamada-san
 - Software update to split ecl and ecltrg data on recl2
 - Update some daq conditionDB files
 - Update and test of ECL run control GUI
 - Thanks to Mikhail
 - Large help and support for several tests and checks
 - Never successfully took GNN data yet
 - Plan
 - Need more test and study
 - Need to prepare unpacker for GNN-ETM and modify unpacker for ETM




GNN-ETM in ehut




Energy gain adjustment

- Installed jumper for 4 ch (4 ShaperDSP) to adjust E gain.
 - Gain for 1 ch was too high
 - ECL experts cut off one of two lines for 3 ch during summer
 - Found 3 ch were unstable due to one of two lines
- Attenuator coefficients were adjusted roughly.
- Plan to perform energy calibration with beam data




- Some channels became noisy
 - Normal TC hit rate for cosmic is 10Hz, but >1000Hz sometimes
 - Noisy channels are all in endcap, and noise level is changing…
 - Example waveform



- At detector, with Hobin Lee(SNU), some checks were done.
 - Confirmed noise is from cables between ShaperDSP and detector
 - Connect and disconnect wires between VME and ShaperDSP for reducing grounding loop, but no difference in noise level was found
 - (Not all noisy channels were tested…)
- For run 2024c, if noise level is kept high, increase TC energy threshold.
 - I will monitor until beam comes.


Event timing DQM

- Event timing DQM were prepared during 2024b run
 - bug was found



- The bugfix and MR are done, and ready for 2024c run.
- Plan
 - Prepare manual
 - Add some parameters to QAM (or mirabelle)
 - Report and discuss with SVD experts for next updates.

Status of problems found from eclmumu bit



- eclmumu bit, generated by ETM and prescale=1 at GDL
 - 165°< $\Sigma\theta_{\rm CM}$ < 190°, where $\Sigma\theta_{\rm CM}$ is sum of polar angles of 2 clusters in CM
 - 160°< $\Delta\phi_{\rm CM}$ < 200°, where $\Delta\phi_{\rm CM}$ is difference of phi angles of 2 clusters in CM
 - E(CL1) < 2 GeV && E(CL2) < 2 GeV
 - where E(CLX) is energy of cluster number X (X=1,2) in CM


Status of problems found from eclmumu bit

- With large contributions from Kang, Yubo, Junhao, and Koga-san,
 - For tsim, bugs were found
 - Affected all ecl trigger bits, but mainly for ecl mumu
 - For FW, wrong cluster energy threshold for exp14-26 were found
 - The threshold was ok for <=exp12 and >=exp27
- Yubo prepared script which check parameter in real data and checked past data if similar problem for other bits exist or not.
 - Fortunately, no problem in other trigger bit was confirmed.
- Bugfix tsim was prepared and it is in release.
- In order to have exp dependent parameter, tsim is updated again.
 - updated tsim is in MR
 - conditionDB related update is in MR
- Plan
 - Complete tsim updates with conditionDB
 - Update ETM SLC to monitor all parameters


Summary / plan

- Summary
 - ECL trigger is ready for 2024c run
 - Updates and bugfixes for hardware, firmware, and software during summer
 - Not all are completed
- Plan
 - investigation of instability of tmm-etm link
 - Preparation of gnn
 - Countermeasure for noisy channels
 - Tsim update
 - TC energy calibration
 - Server OS update
 - Beam background study

Backup




Forward endcap




FAM	Sector	Cable	Crate(cable)
1	F1	F1	FE1(6-10)
2	F2	F2	FE2(1-5)
	F3	F3	FE2(6-10)
3	F4	F4	FE3(1-5)
	F5	F5	FE3(6-10)
4	F6	F6	FE4(1-5)
	F7	F7	FE4(6-10)
5	F8	F8	FE5(1-5)
	F9	F9	FE5(6-10)
6	F10	F10	FE6(1-5)
	F11	F11	FE6(6-10)
7	F12	F12	FE7(1-5)
	F13	F13	FE7(6-10)
8	F14	F14	FE8(1-5)
	F15	F15	FE8(6-10)
1	F16	F16	FE1(1-5)

backward endcap




Problem in eclmumu bit




- eclmumu bit, generated by ETM and prescale=1 at GDL
 - 165°< $\Sigma \theta_{\rm CM}$ < 190°, where $\Sigma \theta_{\rm CM}$ is sum of polar angles of 2 clusters in CM
 - 160°< $\Delta\phi_{\rm CM}$ < 200°, where $\Delta\phi_{\rm CM}$ is difference of phi angles of 2 clusters in CM
 - E(CL1) < 2 GeV && E(CL2) < 2 GeV
 - where E(CLX) is energy of cluster number X (X=1,2) in CM

eclmumu e12r6399




eclmumu e14r799



• Same bad results continue for run of exp26

eclmumu e30r165



- From the beginning of exp30 to now, we have correct results as same as exp12.
- From exp30, started using UT4, and online software was updated.

Plan

- · It's still unclear why wrong parameter was used
 - ETM(UT3), SLC, and online-lib were updated many times, but not all were saved
- Need to update SLC
 - Consistency check between loaded and read parameters is not done on ETM
 - In FAM case, it's done on SLC for all(?) parameters, and error signal is issued if inconsistent is detected.
 - Bad parameter names in SLC are subject to error
 - 2d_bhabha, bhabha1, bhabha_3d, bhabha2,,,
 - eclmumu parameters are in array of bhabha2 and bhabha_3d
- Make python script to check all parameters from raw data
 - Run this script when new exp start after shutdown or big updates
 - Check parameters of ETM for past exp data