

Status of PXD2

Fabian Becherer
on behalf of the PXD group


Deutsches Elektronen Synchrotron, DESY
Belle II Experiment, KEK

September 25, 2023



HELMHOLTZ

- Both HS tested at DESY
 - Two inner ladders of 1st HS broke
 - Rebuild HS with additional optimizations
 - Applied also modifications to 2nd HS




Pedestal comparison before and after HS Commissioning - Module W07_IP






Pedestal comparison before and after HS Commissioning - Module W09_IB

- Pedestals and source scan taken
- Stable working conditions for both HS found
- For one HS isolation to beam-pipe broken
- Significant bending observed for edge L2 ladders
 - Unclear if caused by setup
- De-commissioning at DESY
- Transport of both HS and services to KEK




- PXD2 mounted on new BP with isolating foil
- Installed camera ring to study bending
- Closed heavy metal end flange
- Environment monitoring and interlock system
- Cooling (CO₂ and N₂)
- Dry volume


PXD2 Monitoring and Alarm System



- Setup of DHH system and connection
 - Preparation of power supplies
 - ▶ Needed power supplies (PS) has been doubled
 - ▶ Several modification and updated necessary for PXD1 PS
 - ▶ With big effort 40 (+10) PS has been collected and modified
 - ▶ Setup of slow control and interlock system
- Talk in hardware session by Jannes



All 40 modules operational





Electrical functionality:

- Turned on of PXD2 step by step
 - ▶ All modules functional
 - ▶ Three L2 modules with known issues
 - ▶ One L1 ladder with new issue



Mechanical behavior:

- Significant ladder bending for L2.7 and L2.8
- Reduced fwd screw torque for these ladders
- Acceptable bending of 500 μm remained
- Bending studies at DESY and PXD1



Temperature behavior:

- Air temperature increased above 30°C
- To high temperature for long term operation
- Reduced CO2 temp. from -20°C to -25°C
- Increased N2 flow rate
→ Air temperature stabilized below 30°C



→ Decision to extract PXD1 and install PXD2

Preparation of SVD:

- VXD extracted from Belle2
- SVD de-attached from PXD1


Final preparations of PXD2 for SVD assembling:

- Re-movement of environment monitoring and cameras
- Installation of 4 FOS fibers (3 from PXD1)
- Preparation of grounding scheme
 - ▶ Isolation to BP again broken
 - ▶ Decision to ground PXD2 to BP
- Solving possible conflicts with SVD





Attachment of SVD:

- SVD was successfully attached

→ Start of VXD commissioning



- New produced FOS fibers for PXD2 calibration issues
- Installed 3 FOS fibers from PXD1 + 1 new FOS fiber (2.9)
- Use cross-calibration for more reliable values
- Use working points at which all FOS fibers should have same temperature
 - ▶ After establishing dry volume
 - ▶ At room temperature
 - ▶ After cooled down when temperature stabilized (before PXD is powered)



Step by step test of both systems:

- Both systems in same state as before


Operation of full system:

- Temperature further increased
 - ▶ Cross-calibrated FOS fibers
 - No direct comparison to NTCs temp.
 - ▶ CO₂ reduced to -30°C
 - ▶ FOS 2.9 center up to 38°C
 - ▶ Optimization of cooling in commissioning setup limited

Conclusion of commissioning:

- Both systems are functional
- PXD2 relative hot (FOS2.9 center)
 - ▶ N₂ flow can be further optimized in Belle2
 - ▶ Estimate exact bending with cosmic data
 - ▶ Possibility to not power all modules

→ Continue with VXD installation



Insertion of VXD:

- Successful without any issues


Installation of cabling:

- Number of PXD cable doubled
- Unused PXD1 space overtaken by other groups
- Esp. on BWD more environment cables as designed
→ Very challenging due to the limited space

Installation of cooling system:

- One CO2 pipe broke twice → Replaced by spare
- Combination of pre-damage and strong bending
- All pipes in final position and pressure tested
→ No further damage likely

→ Start with VXD commissioning in Belle2





Conflicts between new PXD cables and other systems?
→ Perform several space tests

Conflicts to QCS:

- Check with tools possible conflicts of inner cables
- Several iteration with optimizations needed

Conflicts to ECL and ARICH:


- Test insertion of ECL (+ARICH) on both sides
- Apart from small optimization smooth insertion
→ Overall much less problems than before phase 3







Thermal behavior:

- Temperature slightly reduced ($\approx 1^\circ\text{C}$)
- Extensive studies to further optimize cooling
- Optimize N₂ flow rate
 - ▶ Increase PXD flow rate
 - ▶ Decrease SVD flow rate
 - Similar total amount compared to phase 3
- FOS 2.9 center could be reduced to 32°C
- Further optimization for beam operation (New hardware will be installed)

→ Temperatures stabilized at acceptable values





Unstable Switcher States in L1.4:

- "good" and "bad" mode
- Problematic gate(s) or switcher?
- Temporary solution by reducing gate-on voltage

Pedestal Glitches:

- Significant pedestal shifts within indiv. frames
- Dominant structure in L2.4 bwd and L2.12 bwd
→ Large noise


→ Needs further investigations

Module performance:

- Esp. L2.12 introduce high noise
 - ▶ DHPs have to reset in short intervals
 - ▶ Increase for now noise threshold
 - ▶ Needs further investigations

- Other modules perform as expected

→ More time need for detailed studies




Alignment data:

- Estimate bending of ladders (esp. L2.7, L2.8)
- Different PXD2 configuration
 - ▶ With(out) partial L2.7 and L2.8

→ Final decision if both ladders will be powered
- First results (36/40) and reduced temperature promising

→ Hopefully L2.7 and L2.8 can be fully operated



PXD2 installation very successful:

- PXD2 installed on new BP and SVD attached
- New VXD inserted into Belle2
- PXD1 services extended for PXD2 → No conflicts



PXD2 behavior:

- All modules are electrical working
- PXD2 produces more head than expected → Cooling optimizations
- Finally temperatures in an acceptable range
- L2.7 and L2.8 ladders with significant bending in B4
 - ▶ First cosmic data and reduce temperature are promising
- Two L2 modules have noise issue
- Two L1 modules have broken gate(s) or switcher

Outlook:







- Cosmic data taking ongoing
- Small modification of N2 hardware will be installed
- Further investigations in problematic modules

→ PXD2 is installed and ready for data taking




Backup


- New produced FOS fibers for PXD2 calibration issues
- Installed 3 FOS fibers from PXD1 + 1 new FOS fiber (2.9)
- Use cross-calibration for more reliable values
- Use working points at which all FOS fibers should have same temperature
 - ▶ After establishing dry volume
 - ▶ At room temperature
 - ▶ After cooled down when temperature stabilized (before PXD is powered)



PXD PEAK and SVD PEAK at -30 C



40/40 PXD, SVD PEAK, -30 C, Belle2, Final N2 settings



Thermal dummy L2 ladder bent with gradually increasing sagitta


- ~ 4500 cycles at $\Delta 0.9$ mm
- ~ 2500 cycles at $\Delta 1.1$ mm
- >100 cycles at 1.8 mm
-> ladder developed two kinks

→ Thermal dummy ladder mechanically different



→ Both kinks at resistor lines

Repeat with recently glued L2 dummy ladder

L2 glue joint endurance test




After more than two months with more than 90k cycles with sagitta >1 mm → Ladder still intact



Raiding the Thermal Mock-up

- Dummy Si ladder with resistors for heating
 - 8.9 W the design power consumption
 - 8 W DHP/DCD



Thermal Impact of the Screw Torque

- Screwed Ladder to cooling block
 - 0.2 cNm \rightarrow 1.4 cNm \rightarrow 0.2 cNm
- IR camera: Temperature measurement of DHP/DCD area
 - 4 ROIs: 3 DHP/DCD, 1 glue joint
 - Kapton: emission 0.9
- Impact observed: $< 2^\circ\text{C}$

