
CDC

Nanae Taniguchi (KEK)

Belle II Trigger and DAQ Workshop 2019

CDC readout



Belle2Link

wire hits \rightarrow CDCTRG


trigger/clock firmware download

ASIC

FADC

power supply

- 14,336 channel
- 299 FEs: 48ch/FE
- 1 FE read 3-layer x 16 cells
- 299 HSLB: 75 coppers
- data sent to DAQ and TRG systems
 - cdc raw data (drift time and dE/ dx) to DAQ
 - timing information to CDCTRG





operation of CDC readout

- DAQ problems of CDC FE
 - known problems occurred before beam ON
 - specific FEs have problems
 - could not be fixed, mask these FEs during phase-3
 - problems occurred during beam ON
 - seems to occur randomly and not occur without beam

CDC front end operation

- 7 FEs are masked during phase-3 physics run
 - #247,204,218 (b2llost): fixed once ~2 years ago, but appear again
 - #37,193 (b2llost) : new
 - #97, 115 (ttlost/crc error/b2link error): new. it was occurred when we had resumed operation with Belle solenoid turned ON
- 1 FE can not be programed via FTSW
 - special treatment with firmware download tool provided by Xilinx (iMPACT)
 - replacement of cat.7 cable may be necessary
- These errors occurred before beam ON





maintenance of FE board

- belle2 link lost (b2llost) problem
 - board (1): #204
 - link lost after 1-2 hours in global cosmic run
 - board (2): #219
 - no b2llost in global cosmic run
 - link lost after ~ 24 hours with high rate test (poisson ~45kHz)
 - board (3): #247
 - no b2llost in global cosmic and recent high rate test
 - We haven't touch this board in September maintenance

b2llost problem



FTSW port is O.K.

It may be a problem of cat.7 (clock timing), but it works after changing combination.

cat.7 cable is not swapped

	optical fiber	cat.7	replace	cat.7
	swap	swap	board	swap
board #219	b2llost		b2llost	
board #218				

FTSW port is not checked.

(work in high place. I'm considering to build a scaffold for safety maintenance work. CDC/TOP)

It may be a problem of cat.7 (clock timing), but it works after changing combination.

- No b2llost in several short(~24h) runs with normal stop at high rate test
- No b2llost in long run > 9 days at high rate test

investigation of b2llost/ttlost

- To check if b2llost is fixed, we can only have test runs for several hours
- Zhou-san suggests a test for investigation of b2llost. We have started to check FEs one by one during summer shutdown.
- (I think) we see features in problematic FEs. We expect to establish a criteria to check b2llost.
- details will be reported by Zhou-san tomorrow
- Kunigo-san is working to study ttlost
 - CDC FE will be tested soon


CDC front end operation

- DAQ errors of CDC FEs during beam ON
 - rerr / fifoerr / semmbe / semcrc
 - SALS(Stop Abort Load Start) doesn't work
 - need to re-program FPGA on FE
 - Unpacker error due to corrupted data
 - load on HLT become heavy
 - SALS doesn't work
 - need to re-program FPGA on FE
 - they seem to occur randomly, not in specific FE

FE error during phase-3 operation

- Error map of FEs
- monitoring errors by statft
 - script is running to check error every 5 sec. If catch error, execute ttaddr -200 -e/-p and make log file
 - mostly continuously running during phase-3
- operation with included in GLOBAL (Apr. 1 June 30)
- Errors
 - rerr x13
 - fifoerr x9
 - semmbe(multi bit error) x1 (20190503, ~14:00), FE#20

FE error during phase-3 operation



- mostly occurred inner part ?
- study for relation with radiation is ongoing
 - background level measured by diamond sensor and neutron detectors

12

FE error during phase-3 operation

```
nanae.taniguchi Owner 午前8時24分

1=13700 reg=17000001 17000001 anyerr b2ldown=0
0=11200 37000002 b2ldown=1
1=11202 57000000 b2ldown=me [14 cpr2063a]

8=19080 reg=17101000 17101000 b2ldown=cA [cpr2063]
Mon Jul 1 08:24:43 JST 2019

[nanae@ttd11 ~]$ /usr/local/bin/jtag-chain-cdc.sh feel
11201 * DEV[0]: xc5vlx155t (02aec093)
11202 * DEV[0]: xc5vlx155t (02aec093)
11203 * DEV[0]: xc5vlx155t (02aec093)
11204 * DEV[0]: xc5vlx155t (02aec093)
11205 * DEV[0]: xc5vlx155t (02aec093)
11206 * DEV[0]: xc5vlx155t (02aec093)
11207 * DEV[0]: xc5vlx155t (02aec093)

optical transceiver 死んだ??
```

stat=18000001 (ff=0 rx=0 pr=0 pt=0 tx=18 linkdown)

HSLB-a version 0.67 / b2link is down


rxdata=bcbf rxlinkdown=0 rxcrcerr=0 feecrcerr=255
event=0 total=0kB
no b2link error ff00 0 datapkt 0 dataword 0

£ XILINX.

Rocket I/O SEU

- b2ldown at ~08:20, 1st July
- not during physics run, but high beam current study was ongoing
- FPGA re-program didn't work
- check optical fiber -> no light from FE
- By power-cycle of DC PS, link is recovered
- Nakao-san suggested it may be Rocket I/O SEU

Figure 1-2 shows a diagram of a GTP_DUAL tile, containing two GTP transceivers and a shared resources block. The GTP_DUAL tile is the HDL primitive used to operate GTP transceivers in the FPGA.



1. CLKIN is a simplification for a clock source. See Figure 5-3, page 81 for details on CLKIN.

Figure 1-2: GTP_DUAL Tile Block Diagram

preparation for autumn run

CDC HV crate CDC excluded from HV master CDC HV control PC HV crate HV module HV module

Leak current can be controlled and HV trip can be occurred easily

HV auto-recovering from trip

 auto recovering was not implemented since we worry about persistent high current

prepare test setup

- we like to keep CDC HV ON for HV test and cosmic run and avoid affecting detector by test of auto-recovering
- CDC is excluded from HV master and independent test setup with dummy load is included

will start with simple function first

- call 'recover' when TRIP detected
- constrain the number of trials if necessary

preparation for autumn run

DQM

- occupancy plot with updated every a few seconds
- requested to understand beam background
- Yin Junhao (IHEP) is working
- QAM / monitoring of run dependence
 - dE/dx: Jitendra Kumar and Roy Briere (CMU)
 - Ks reconstruction, decay inside CDC to check performance CDC only: Makoto Uchida (TIT)

summary

- CDC readout work basically during phase-3
- Although 7 FEs are masked, impact on performance is not so large
- We have progress in investigation for DAQ errors of FE
- During summer shutdown, we will implement HV autorecovering and improve DQM/run-dependent monitoring