

News from KEK

Michele & Seema
ISU KLM Meeting
30/09/2022

Introduction


- Inspected bubbler signals in BB2 inner & outer return panels (odd channel numbers {3,5..29} on circuit)
 - Most channels show “standard” pulse (see next slide)
 - Some channels show a “low” pulse (ch. 7, 11, 13, 15, 17 of BB2 inner side)
 - Some “noisy” channels (need to double check probe connection)
 - No signal in channels 29 inner/return (stable flat baseline voltage at 1V)
- Difficult to measure signal from other sectors due to very low bubbles rate
 - Tried a few in BB1 outer return, which were showing a “standard” pulse
 - Sumisawa-san will close the N2 gas flow for all inner RPCs, thus doubling the flow rate for all outer RPCs (10%→20% wrt nominal)
 - To test the supply side, we can use a mechanical pump with a connector to the bubbler panels

Pulses in BB2


“Standard”





“Low”



“Noisy”



Gap in sensor support



- There seems to be a gap between the tubes and the LED sensor support structure
- Difficult to tell from the panels with oil

Backup