


KLM Bubbler updates

return side bubbler flowrates

Michele, Noah, Sayan, Soeren; 18th October, 2023

- Plots on indico
- Data from four channels connected to board 5
 - BB3, BB4 return side bubblers conected



0	BB3 Inner Return
1	BB4 Inner Return
3	BB3 outer return
4	BB4 outer return

- Burnt ribbon cable on board 1(fixed)
 - One of 40 ribbon cables' plastic melted
 - Happened while running, closing the enclosure
 - Due to open power cable shorting with ground
- One of 2 fuses blown on board 5(not fixed)
 - Observed immediately on testing
 - No power to readout board, only pi receiving power



- Burnt ribbon cable on board 1(fixed)
 - One of 40 ribbon cables' plastic melted
 - Happened while running, closing the enclosure
 - Due to open power cable shorting with ground
- One of 2 fuses blown on board 5(not fixed)
 - Observed immediately on testing
 - No power to readout board, only pi receiving power

