


Monitoring updates

KLM

Sayan Mitra, 29th November, 2023

- Updated thresholds for BB5
 - Bubble signal height is lower: 1.4 V (other sectors have more than 2 V)
- Replaced faulty cable for BB4OS



Picture of enclosure

